

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 08/23/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 1200, 08/23/12 – 1200, 09/06/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Aerial Field Observer	Houston, TX
8. Activity Log			
Time	Major Events		
	<b>Operational Observation:</b>		
0730	<ul style="list-style-type: none"> <li>Arrived at the ICP</li> <li>Began the production of the Situational Photolog for the EPA C&amp;G.</li> </ul>		
0800	<ul style="list-style-type: none"> <li>Attended the EPA C&amp;G meeting.</li> </ul>		
0900	<ul style="list-style-type: none"> <li>Arrived at C0.4 Boat Launch and launched the boat.</li> <li>Observed spots of tar globs and silver sheen around the C0.4 boat launch.</li> <li>MP5.0 – MP5.63 LDB observed tar globs and sheen.</li> <li>MP5.55 observed a poling crew operating.</li> <li>MP5.63 LDB observed a very small area of silver sheen.</li> <li>Ceresco Dam observed the sheen sweep boat performing boom maintenance.</li> <li>MP5.7 – MP5.55 RDB observed silver sheen.</li> <li>MP5.0 LDB observed second poling crew operating.</li> <li>MP4.5 below the former Island F observed sheen. The quantity of sheen observed did not warrant a sweep boat.</li> <li>Observed heavy rainbow and silver sheen downstream from the poling crew at MP5.0LDB.</li> </ul>		
10:30	<ul style="list-style-type: none"> <li>Pulled the boat and relocated to Shady Bend Campground boat launch</li> <li>MP15.5 South Mill Pond observed small ribbons of sheen flowing out of the south Mill Pond.</li> <li>MP21.5 observed the river bank erosion inspecting teams.</li> <li>MP21.5 Custer Drive Bridge observed ribbons of sheen. The quantity of sheen did not meet the requirements for a sheen sweep boat.</li> <li>Shady Bend Campground observed conifers staged for installation of future sediment traps.</li> <li>MP26.25 RDB no sheen observed.</li> <li>MP26.0 RDB no sheen observed.</li> <li>MP23.10 RDB no sheen observed.</li> <li>MP30.8 LDB no sheen observed.</li> <li>MP36.25 area where ribbons of sheen were observed. The quantity of sheen did not meet the requirements for a sheen sweep boat.</li> </ul>		
14:30	<ul style="list-style-type: none"> <li>Pulled the boat out at E4, boat driver was having issues with the engine.</li> <li>MP21.0 LDB observed a LSR poling crew.</li> <li>Portage launch below Ceresco Dam, sheen observed. The quantity of sheen did not meet the requirements for a sheen sweep boat.</li> <li>Ceresco Dam portage kiosk materials have been added. No decontamination station observed.</li> </ul>		
15:30	<ul style="list-style-type: none"> <li>Return to the ICP and began daily photo log.</li> </ul>		

	<b>Planning Activities:</b> <ul style="list-style-type: none"><li>• Completed 214</li><li>• Prepared and distributed Daily Situation Unit Photo Log.</li><li>• Continued writing the SitRep.</li></ul>
9.	Prepared by (Name and Position) Matthew Haak, Situation Unit, USEPA-START